

Port of Garston

NOTICE TO MARINERS No 009 of 2021

Damaged Dock Ladder

NOTICE IS HEREBY GIVEN that as stated in NTM No.006 of 2021 vessels are advised to use fendering when berthing alongside a quay wall with a none recessed fixed ladder. This specific ladder in picture below is located approximately 30m from the Eastern corner of Coal berth in Stalbridge Dock. The ladder is protruding up to 30cm from the wall.



Mariners are advised to contact “Stalbridge Lock” on VHF Channel 20 before entering the Garston Channel for further information.

This will remain in place until further notice.

Callum Coulbeck

Assistant Dock Master, Garston

4th August 2021